

FMC Corporation

Phosphorus Chemicals Division
PO Box 4111
Pocatello, Idaho 83205
(208) 236-8200

RECEIVED
APR 08 2002

FMC

IDD 9518
FF17a
4-3-02

April 3, 2002

Ms. Linda Meyer
Office of Waste and Chemical Management (HW-124)
US Environmental Protection Agency
1200 Sixth Avenue
Seattle, WA 98101

FILE COPY

Re: FMC Idaho LLC., EPA ID No. IDD 07092 9518
Pond 8S and Pond 9E Post-Closure Monitoring and Inspection Summaries for 2001

Dear Ms. Meyer:

Please find enclosed the Pond 8S and Pond 9E Post-Closure Monitoring and Inspection Summaries for 2001. These reports are being submitted to EPA for information purposes only.

Two years of post-closure monitoring has been completed at pond 8S and one year of post-closure monitoring has been completed at pond 9E. Overall, acceptable conditions were noted throughout the monitoring period for the final cover and monitoring systems at both pond 8S and pond 9E. No temperature or pressure alarms were triggered at either pond 8S or pond 9E during the monitoring period. No water was pumped from the cap drainage subdrain outlets #1 or #2 at pond 8S; therefore, the total cap drainage/infiltration rate at pond 8S remained zero for the monitoring period.

Per the pond 8S and pond 9E post-closure plans, post-closure monitoring will continue at these units. If you have any questions, please feel free to contact me at (208) 236-8216.

Very truly yours,



Rob J. Hartman
FMC Corporation

Enclosure

FILE COPY